CORPUS CHRISTI CHANNEL DEPTHS
TABULATED FROM SURVEYS BY THE CORPS OF ENGINEERS - REPORT OF FEB-APR 2015

NAME OF CHANNEL	LEFT OUTSIDE QUARTER	LEFT INSIDE QUARTER	RIGHT INSIDE QUARTER	RIGHT OUTSIDE QUARTER	DATE OF SURVEY	WIDTH (FEET)	LENGTH (NAUT MILES)	DEPTH MLLW (FEET)
ARANSAS PASS: SEA BAR CHANNEL	46.0	47.0	48.0	45.0	3-15	700-600	2.79	47
JETTY CHANNEL	55.0	51.0	49.0	48.0	3-15	600	1.28	47-45
INNER BASIN MAIN CHANNEL	50.0	57.0	57.0	53.0	3-15	600-728	0.40	45
INNER BASIN AT HARBOR ISLAND	41.0	52.0	53.0	35.0	3-15	600-1559	0.32	45
HUMBLE BASIN TO JCT LA QUINTA CH	33.0	45.0	46.0	44.0	3-15	600-500	10.0	45
LA QUINTA CH JCT TO BCN 82	43.0	48.0	48.0	44.0	3-15	400	9.66	45
CHANNEL TO LA QUINTA	43.4	44.5	45.0	42.5	4-14	300-400	5.31	45

NOTE - CONSULT THE CORPS OF ENGINEERS FOR CHANGES SUBSEQUENT TO THE ABOVE INFORMATION

TIDAL INFORMATION

NAME	(LAT/LONG)	Mean Higher High Water (feet)	Mean High Water (feet)	Mean Low Water (feet)
Port Aransas Channel	(27°50'N/097°03'W)	1.4	---	---

Dashes (- - -) located in datum columns indicate unavailable datum values for a tide station. Real-time water levels, tide predictions, and tidal current predictions are available on the Internet from http://tidesandcurrents.noaa.gov. (Jul 2015)

SOURCE

A	1990-2006	NOS Surveys	full bottom coverage
B1	1990-1993	NOS Surveys	partial bottom coverage
B2	1970-1989	NOS Surveys	partial bottom coverage
B4	1900-1939	NOS Surveys	partial bottom coverage

6th Ed., Aug. 2015
11312
Last Correction: 10/7/2015. Cleared through:
LNM: 3915 (9/29/2015), NM: 3915 (9/26/2015)

To ensure that this chart was printed at the proper scale, the line below should measure six inches (152 millimeters).
If the line does not measure six inches (152 millimeters), this copy is not certified safe for navigation.

CAUTION
This chart has been corrected from the Notice to Mariners (NM) published weekly by the National Geospatial-Intelligence Agency and the Local Notice to Mariners (LNM) issued periodically by each U.S. Coast Guard district to the dates shown in the lower left hand corner. Chart updates corrected from Notice to Mariners published after the dates shown in the lower left hand corner are available at nauticalcharts.noaa.gov.

NOAA encourages users to submit inquiries, discrepancies or comments about this chart at http://www.nauticalcharts.noaa.gov/staff/contact.htm.

This chart was distributed as a PDF (Portable Document Format). Printing PDFs may alter the chart scale, color, or legibility that may impact suitability for navigation. Printed charts provided by NOAA certified Print on Demand (POD) providers fulfill a vessel's requirement to carry a navigational chart "published by the National Ocean Service" in accordance with federal regulations, including but not limited to 33 C.F.R. 164.33(a), 33 C.F.R. 164.72(b), and 46 C.F.R. 28.225(a). POD charts meet stringent print standards and can be recognized by an official certification of authenticity printed on the chart. A list of POD providers can be found at: nauticalcharts.noaa.gov/pod

Published at Washington, D.C.
U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SERVICE
COAST SURVEY