MOBILE BAY AND RIVER CHANNEL DEPTHS TABULATED FROM SURVEYS BY THE CORPS OF ENGINEERS - REPORT OF JUN 2016 SURVEYS TO DEC 2015							
CONTROLLING DEPTHS FROM SEAWARD IN FEET AT MEAN LOWER LOW WATER (MLLW)					PROJECT DIMENSIONS		
NAME OF CHANNEL	LEFT OUTSIDE QUARTER	MIDDLE HALF OF CHANNEL	RIGHT OUTSIDE QUARTER	DATE OF SURVEY	WIDTH (FEET)	LENGTH (MILES)	DEPTH MLLW (FEET)
MOBILE BAY:							
LOWER BAY (TO LIGHT 50)	42.6A	45.0	41.1	4-16	400	13.3	45
UPPER BAY	38.3	42.2	42.1B	6-16	400	15.4	45
THEODORE SHIP CHANNEL:							
BAY CUT	38.9C	39.5	38.5	4-16	400	5.3	40
ANCHORAGE AREA	37.2	39.8	40.4	10-15	300	0.2	40
LAND CUT	37.1	40.0	38.3	4-16	300	1.7	40
TURNING BASIN	35.9	35.6	32.5	4-16	1400	0.3	40
BARGE CHANNEL	8.9	11.5	10.8	1-16	100	1.3	12

A. EXCEPT FOR SHOALING TO 39.8 FEET IN BEND WIDENING AREA.
B. EXCEPT FOR SHOALING TO 39.4 FEET IN BEND WIDENING AREA.
C. EXCEPT FOR SHOALING TO 38.0 FEET IN BEND WIDENING AREA.

NOTE - CONSULT THE CORPS OF ENGINEERS FOR CHANGES SUBSEQUENT TO THE ABOVE INFORMATION

HURRICANES AND TROPICAL STORMS

Hurricanes, tropical storms and other major storms may cause considerable damage to marine structures, aids to navigation and moored vessels, resulting in submerged debris in unknown locations.

Charted soundings, channel depths and shoreline may not reflect actual conditions following these storms. Fixed aids to navigation may have been damaged or destroyed. Buoys may have been moved from their charted positions, damaged, sunk, extinguished or otherwise made inoperative. Mariners should not rely upon the position or operation of an aid to navigation. Wrecks and submerged obstructions may have been displaced from charted locations. Pipelines may have become uncovered or moved.

Mariners are urged to exercise extreme caution and are requested to report aids to navigation discrepancies and hazards to navigation to the nearest United States Coast Guard unit.

NOAA encourages users to submit inquiries, discrepancies or comments about this chart at http://www.nauticalcharts.noaa.gov/staff/contact.htm.

Formerly 11379, 1st Ed., Apr. 1991 KAPP 2888

SOUNDINGS IN FEET

11380



4th Ed., Nov./ 2015
11380

CAUTION

This chart has been corrected from the Notice to Mariners (NM) published weekly by the National Geospatial-Intelligence Agency and the Local Notice to Mariners (LNM) issued periodically by each U.S. Coast Guard district to the dates shown in the lower left hand corner. Chart updates corrected from Notice to Mariners published after the dates shown in the lower left hand corner are available at nauticalcharts.noaa.gov.

Last Correction: 11/9/2016. Cleared through:
LNM: 4416 (11/1/2016), NM: 4316 (10/22/2016)

To ensure that this chart was printed at the proper scale, the line below should measure six inches (152 millimeters).
If the line does not measure six inches (152 millimeters), this copy is not certified safe for navigation.

SOUNDINGS IN FEET

Published at Washington, D.C.
U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SERVICE
COAST SURVEY

FATHOMS / FEET / METERS

East Fowl River To Deer River Pt
SOUNDINGS IN FEET - SCALE 1:20,000

11380

This chart was distributed as a PDF (Portable Document Format). Printing PDFs may alter the chart scale, color, or legibility that may impact suitability for navigation. Printed charts provided by NOAA certified Print on Demand (POD) providers fulfill a vessel's requirement to carry a navigational chart "published by the National Ocean Service" in accordance with federal regulations, including but not limited to 33 C.F.R. 164.33(a), 33 C.F.R. 164.72(b), and 46 C.F.R. 28.225(a). POD charts meet stringent print standards and can be recognized by an official certification of authenticity printed on the chart. A list of POD providers can be found at: nauticalcharts.noaa.gov/pod